	CENTRAL INTELLIGENCE AGENC	Y REPORT NO.	
	INFORMATION REPO		
COUNTRY USS	en e	DATE DISTR. M Aug 1953	e '' ,'.
SUBJECT Loc	comotive Maintenance in Orel	NO. OF PAGES 2	
PLACE 25X1 ACQUIRED		NO. OF ENCLS.	25X1
DATE ACQUIRED BY SO	DURCE Sept 1943 and earlier	SUPPLEMENT TO REPORT NO.	
DATE OF INFO	, , , , , , , , , , , , , , , , , , , ,	vr	
Tota battores coay of Tot wested size and Tota of the or and Tota of the destruct to a consecutor of Lag. Tota our	25X1	IS UNEVALUATED INFORMATION	
serviced locomot depot a serviced locomotive was serunning from the	depot in the south-east corner of Orel. ives operating between Kursk and Tula. locomotive took the place of the haulin ent to the service yard for inspection. depot to the service yard. In the service, each section capable of holding three	As each train arrived at the ag locomotive and the hauling. There were eight sets of track rice yard there was a round-house.	
in the crews were tives in from ter following: Check lines, checking v and bearings. Be	king boilers, checking instruments, check water pumps, checking <u>coal and oil</u> delive etween 1935 and 1943 nd ga- ives per day. The locomotives were divide	and make minor repairs to locomo- responsible for one of the king brakes, checking steam ery systems and checking shafts we minor service to approximately	
in the crews were tives in from ter following: Checking wand bearings. Be 60 to 65 locomotitrains and freight Up to 1940 about these were seen than oil in our of the boiler on each tive, a serial mu of the locomotive.	e specialists and were able to inspect a n minutes to two hours. Each crew was king boilers, checking instruments, checking boilers, checking coal and oil deliveration of the coal and oil deliverati	and make minor repairs to locomo- responsible for one of the king brakes, checking steam ery systems and checking shafts ve minor service to approximately ded equally between passenger ere inspected daily but none of ecause coal was more plentiful on the engineer's door, or on y of manufacture of the locomo- nufacture. I remember that most	
in the crews were tives in from ter following: Checking wand bearings. Be 60 to 65 locomotitrains and freight Up to 1940 about these were seen than oil in our of the boiler on each tive, a serial must be a serial must be futilowsk or Kram. It was required to service yard for	e specialists and were able to inspect a minutes to two hours. Each crew was king boilers, checking instruments, checking boilers, checking coal and oil deliverative of the locomotives were divided trains. three or four oil-burning locomotives were fiter 1940. I was told this was beforea. The locomotives had brass plates of side of the locomotive giving the citymber, and the day, month and year of makes were manufactured in Bryansk or Khark	and make minor repairs to locomoresponsible for one of the king brakes, checking steam ery systems and checking shafts we minor service the approximately ded equally between passenger ere inspected daily but none of ecause coal was more plentiful on the engineer's door, or on y of manufacture of the locomonufacture. I remember that most now with the remainder coming from	
in the crews were tives in from ter following: Checking wand bearings. Be 60 to 65 locomotitrains and freight Up to 1940 about these were seen than oil in our of the boiler on each tive, a serial must be a serial must be futilowsk or Kram. It was required to service yard for	e specialists and were able to inspect a n minutes to two hours. Each crew was king bollers, checking instruments, checking bollers, checking coal and oil delive exteen 1935 and 1943 and gaives per day. The locomotives were divident trains. three or four oil-burning locomotives we fiter 1940. I was told this was because. The locomotives had brass plates on side of the locomotive giving the city amber, and the day, month and year of many es were manufactured in Bryansk or Khark eatorvka-Nikitovka-Gorlovka. The regulation that each locomotive passing inspection. Replacement locomotives were manufactured in Bryansk or Khark eatorvka-Nikitovka-Gorlovka.	and make minor repairs to locomoresponsible for one of the king brakes, checking steam ery systems and checking shafts we minor service the approximately ded equally between passenger ere inspected daily but none of ecause coal was more plentiful on the engineer's door, or on y of manufacture of the locomonufacture. I remember that most now with the remainder coming from	•

25X1

25X1

25X1

Sanitiz	ed Copy Approved for Release 2011/07/21 : CIA-RDP80-00809A000600040393-2	
I	22 32pjpp. 3734 15. 1. (153455 25 . 1757 27	25X1
	COMFIDENTIAL.	25X1
		·
<i>*</i> • 5•	It was required that each locomotive be sent into the shop for inspection and major overhaul every 32,000 kilometers. The locomotive engineer was always ready to abide by this regulation because he got a month's vacation while his locomotive was being repaired. Also, the engineer was solely responsible for any injury to the locomotive after the 32,000 kilometers and before the inspection. On the average locomotives travelled 32,000 kilometers in 30 days although I remember that once every month or two a locomotive would come in with only 21 days time.	
6.	The turntable in the round house was turned by hand. In one section of the roundhouse a large crane was used to lift boilers off locomotives. The shops were heated by steam and movable coal stoves. In the wintertime it was so cold that the men carried coal stoves around with them while they were working.	05)/4
7.	there was a major repair shop for locomotives somewhere in Bryansk. There were always five or six locomotives in this shop for major repairs and that the average time for repair was one month. About 30 to 35 men were employed in this shop.	25X1
8.	I never heard of a locomotive being junked. If by cannibalization and servicing with machine shop facilities in Bryansk the locomotive could not be made servicable, it was returned to the factory. There were three lathes working 24 hours per day in the Bryansk repair shop. There was little damage to the service shops at the time of the German attack. As the Soviets retreated from the German attack everything movable in the service of was noved and sent to the Urals. The Germans brought equipment to Orel and Bryansk. When the Germans retreated from Orel they loaded everything movable in trains, including the workers. When we were about three kilometers away from the service shop we looked back and saw big explosions but I have no idea how much damage was done.	
	- end -	
		1
. *		
•		
•		

25X1 25X1

1

25X1

COMPTERMETAL